

Accomplishment Num	Activity	Chainage From	Chainage To	Comments	Date	Lane	Schedule	Work Order Number
AC02137	10100	34.88	34.88	Edge Repair	28/Jul/2016	2	2	
AC03453	10200	22.00	22.00	Edge Repair	25/May/2017	U	2	
AC02533	10500	27.10	27.10	Pothole Repair	17/Oct/2016	1	2	WO00590
AC03173	10500	27.40	27.42	Pothole	08/Feb/2017	2	2	WO00757
AC02527	10500	43.46	43.46	Pothole Repair	17/Oct/2016	2	2	WO00590
AC03252	10500	50.61	50.10	Pothole Repair	06/Mar/2017	1	2	WO00780
AC02820	10500	54.16	54.16	pothole	06/Dec/2016	1	2	WO00590
AC02717	10500	59.72	59.72	Pothole Repair	25/Nov/2016	1	2	WO00607
AC02529	10500	59.73	59.73	Pothole has been done.	17/Oct/2016	1	2	
AC03172	10500	60.41	60.41	Pothole	08/Feb/2017	1	2	WO00757
AC02530	10500	64.05	64.05	Pothole Repair	17/Oct/2016	X	2	WO00590
AC03254	10500	64.087	64.087	Pothole Repair	06/Mar/2017	1	2	WO00780
AC02837	10500	64.14	64.14	Pothole Repair	08/Dec/2016	1	2	WO00687
AC02531	10500	64.92	64.92	Pothole Repair	17/Oct/2016	2	2	WO00590
AC03518	10500	71.34	71.34	pothole	13/Jun/2017	1	2	
AC03169	10500	72.46	72.46	Pothole is very large needs major repairs on top of a blind crest need Traffic control.DUPLICATE	08/Feb/2017	1	2	WO00757
AC03241	10500	72.48	72.48	Pavement failure	06/Mar/2017	1	2	WO00780
AC03170	10500	72.49	72.49	Pothole Repair	08/Feb/2017	1	2	WO00757
AC03171	10500	72.49	72.49	Large pothole	08/Feb/2017	2	2	
AC02532	10500	72.75	72.75	Pothole Repair	17/Oct/2016	1	2	WO00590
AC02309	10500	73.11	73.11	potholes	08/Sep/2016	1	2	WO00590
AC02384	11200	20.20	20.20	Surface Correction	30/Sep/2016	1	2	WO00557
AC02984	13000	46.57	46.57	Surface Correction	17/Jan/2017	2	2	
AC03127	13700	64.89	64.99	rutting 50mm deep in Owp x 47 mtrs long x 60mm deep DUPLICATE	17/Jan/2017	2	2	
AC02535	13900	25.60	25.60	Remove Debris & Stone from Roadway	17/Oct/2016	X	2	WO00602
AC02908	13900	72.48	72.48	Pavement Repairs	13/Dec/2016	1	2	WO00695
AC02298	14000	59.74	59.74	Pavement Repairs	08/Sep/2016	1	2	
AC02620	14350	59.72	59.72	Pavement Repairs	01/Nov/2016	1	2	WO00612
AC03126	14350	64.91	65.06	Failure repaired under another defect. Acc WO 612	17/Jan/2017	2	2	WO00612
AC02979	20300	30.60	30.60	Grading	30/Dec/2016	1	2	
AC03455	32900	70.97	70.97	pipe seperation	26/May/2017	2	2	WO00793
AC03257	40100	21.98	73.55	slashing DUPLICATE	07/Mar/2017	X	2	
AC01879	40100	23.347	76.426	Road Side Slashing - Opal Holding	10/Jun/2016	X	2	WO00469
AC02689	40100	23.347	76.426	Road Side Slashing - Opal Holding	16/Nov/2016	X	2	WO00616
AC03386	40100	23.347	76.426	slashing required	11/May/2017	X	2	WO00785
AC02234	40500	33.208	33.208	Sheep On Road	31/Aug/2016	X	2	
AC03388	40500	35.054	35.054	Tree Over Road	11/May/2017	X	2	WO00800
AC02981	40700	41.20	41.20	Herbicide Spraying	17/Jan/2017	2	2	
AC02297	42900	32.47	32.47	fixed the worst of them need traffic control and hot mix truck for the rest	08/Sep/2016	X	2	
AC02074	42900	56.41	56.41	Repair Pipe Separation	12/Jul/2016	1	2	WO00002
AC03313	45000	20.551	25.69	Call Out Cattle on Road	13/Apr/2017	X	6	WO00758
AC02840	45000	21.309	21.40	Dawson Hwy Call Out Deceased Kangaroo on Roadway	09/Dec/2016	X	6	WO00689
AC02685	45000	21.87	23.347	Call Out - Cattle On Road	15/Nov/2016	X	6	WO00638
AC03239	45000	22.313	22.313	Call Out	06/Mar/2017	X	6	WO00723
AC02152	45000	23.97	24.00	Call out - cattle on road - Reg surfaces	09/Aug/2016	X	6	WO00462

AC02653	45000	23.97	24.00 Call out - cattle on road - Reg surfaces	11/Nov/2016	X	6	
AC02646	45000	23.97	24.00 Call out - cattle on road - Reg surfaces DUPLICATE	11/Nov/2016	X	6	
AC03454	45000	25.69	31.555 Call Out Cattle on Road Dawson Hwy	26/May/2017	X	6	WO00853
AC03137	45000	25.69	27.175 Call Out Cattle on Road	23/Jan/2017	X	6	
AC02153	45000	27.18	30.128 Call Out	09/Aug/2016	X	6	WO00543
AC03262	45000	30.24	30.24 Tree over the road reported by Propel 5:00 am 15/3/17. Terry Ware and Jayson Keyworth attended to remove tree ensuing	16/Mar/2017	X	6	
AC03506	45000	30.47	30.47 Call out Tree over Road 5:00 am Wednesday 15/3/17 - Jayson Keyworth and Terry Ware attended (10hr break resulted)	06/Jun/2017	X	6	WO00803
AC02441	45000	30.675	33.163 CSR 387022 - Dawson Higway, Calliope - Chainage 30.675 to 33.163 - attended at 19:20, 31/7/16 - contractor	05/Oct/2016	X	6	WO00543
AC02647	45000	31.555	34.059 Call Out - Cattle On Road	11/Nov/2016	X	6	WO00543
AC02079	45000	31.80	34.059 Call Out - Cattle On Road	12/Jul/2016	X	6	WO00006
AC02215	45000	34.059	34.059 Call out - CSR 383675 tree over driveway - Jayson Keyworth attended	15/Aug/2016	4	6	WO00553
AC02364	45000	34.20	34.20 Clear Debris from Road Way following Truck Rollover	15/Sep/2016	1	5	WO00564
AC02687	45000	34.99	37.288 Call Out - Cattle On Road csr 410307	15/Nov/2016	X	6	WO00640
AC03436	45000	42.107	42.907 CSR 447034 - Water over road approx 800m west Cat Fish Creek - Dave Hargreaves attended	19/May/2017	X	6	WO00829
AC02216	45000	42.681	42.681 Call out - CSR 383519 debris over road - Jayson Keyworth attended - all lanes	15/Aug/2016	x	6	WO00552
AC02678	45000	58.87	64.483 Call Out - Cattle On Road csr 408818	14/Nov/2016	X	6	WO00623
AC02669	45000	64.44	69.839 Call out 08/10/16	14/Nov/2016	X	6	WO00606
AC03452	45200	22.08	22.08 Call Out	24/May/2017	1	6	
AC02811	50200	20.69	20.69 Sign Maintenance	02/Dec/2016	E	2	WO00677
AC02810	50200	20.96	20.96 Sign Maintenance	02/Dec/2016	U	2	WO00677
AC02911	50200	21.06	21.06 Sign Maintenance	19/Dec/2016	1	2	WO00677
AC02179	50200	22.80	22.80 side road junction left sign not class 1 W2-4B	11/Aug/2016	1	2	
AC02814	50200	23.13	23.13 Sign Maintenance	02/Dec/2016	U	2	WO00677
AC02813	50200	23.40	23.40 Sign Maintenance	02/Dec/2016	U	2	WO00677
AC02912	50200	24.42	24.42 Sign Maintenance	19/Dec/2016	U	2	WO00677
AC02812	50200	28.49	28.49 Sign Maintenance	02/Dec/2016	2	2	WO00677
AC02436	50200	33.00	33.00 Complete under WO 30.0003875	05/Oct/2016	1	2	
AC02815	50200	36.88	36.88 Sign Maintenance	02/Dec/2016	1	2	WO00677
AC02913	50200	39.65	39.65 Sign Maintenance	19/Dec/2016	1	2	WO00677
AC02958	50200	39.83	39.83 Sign Maintenance	11/Jan/2017	1	2	WO00677
AC02932	50200	42.08	42.08 Sign Maintenance	11/Jan/2017	X	2	WO00677
AC02931	50200	43.56	43.56 replaced 2x left 2x right	11/Jan/2017	X	2	WO00677
AC02823	50200	48.39	48.39 Sign Maintenance	07/Dec/2016	2	2	WO00677
AC03159	50200	52.31	52.31 Stock sign missing	02/Feb/2017	2	2	WO00677
AC02821	50200	58.74	58.74 Sign Maintenance	07/Dec/2016	2	2	WO00677
AC02253	50900	34.14	34.14 Sign Maintenance	07/Sep/2016	2	2	
AC02982	50900	42.20	42.20 Sign Maintenance	17/Jan/2017	1	2	
AC02983	50900	43.68	43.68 Sign Maintenance	17/Jan/2017	1	2	
AC02822	50900	52.30	52.30 installed new stock sign	07/Dec/2016		2	
AC02592	51200	22.14	22.14 Guide Post Maintenance	31/Oct/2016	2	2	WO00633
AC02605	51200	24.09	24.09 Guide Post Maintenance	31/Oct/2016	2	2	WO00633
AC02604	51200	24.13	24.13 Guide Post Maintenance	31/Oct/2016	2	2	WO00633
AC02603	51200	24.14	24.14 Guide Post Maintenance	31/Oct/2016	2	2	WO00633
AC02602	51200	24.43	24.43 Guide Post Maintenance	31/Oct/2016	2	2	WO00633
AC03426	51200	25.49	25.49 Guide Post Maintenance	18/May/2017	2	2	WO00858
AC02593	51200	25.84	25.84 Guide Post Maintenance	31/Oct/2016	1	2	WO00633

AC03427	51200	25.85	25.85 Guide Post Maintenance	18/May/2017	2	2	WO00858
AC02007	51200	26.20	26.20 Guide Post Maintenance	07/Jul/2016	1	2	WO00529
AC03428	51200	26.81	26.81 Guide Post Maintenance	18/May/2017	1	2	WO00858
AC03429	51200	27.03	27.03 Guide Post Maintenance	18/May/2017	1	2	WO00858
AC02595	51200	27.04	27.04 Guide Post Maintenance	31/Oct/2016	1	2	WO00633
AC02252	51200	27.05	27.05 Guide Post Maintenance	07/Sep/2016	1	2	
AC02594	51200	27.05	27.05 Guide Post Maintenance	31/Oct/2016	1	2	WO00633
AC02596	51200	32.96	32.96 Guide Post Maintenance	31/Oct/2016	1	2	WO00633
AC02597	51200	32.98	32.98 Guide Post Maintenance	31/Oct/2016	1	2	WO00633
AC02568	51200	33.01	33.01 Guide Post Maintenance	31/Oct/2016	1	2	WO00633
AC02567	51200	33.02	33.02 Guide Post Maintenance	31/Oct/2016	1	2	WO00633
AC02008	51200	33.98	33.98 Guide Post Maintenance	07/Jul/2016	2	2	WO00529
AC02181	51200	34.20	34.20 Guide Post Maintenance	11/Aug/2016	1	2	
AC03430	51200	34.48	34.48 Guide Post Maintenance	18/May/2017	1	2	WO00858
AC02598	51200	34.81	34.81 Guide Post Maintenance	31/Oct/2016	2	2	WO00633
AC02599	51200	35.44	35.44 Guide Post Maintenance	31/Oct/2016	1	2	WO00633
AC03431	51200	38.04	38.04 Guide Post Maintenance	18/May/2017	1	2	WO00858
AC02015	51200	43.81	43.81 Guide Post Maintenance	07/Jul/2016	1	2	WO00529
AC02600	51200	44.86	44.86 Guide Post Maintenance	31/Oct/2016	2	2	WO00633
AC02601	51200	48.54	48.54 Guide Post Maintenance	31/Oct/2016	2	2	WO00633
AC02606	51200	50.05	50.05 Guide Post Maintenance	01/Nov/2016	1	2	WO00633
AC02607	51200	60.85	60.85 Guide Post Maintenance	01/Nov/2016	1	2	WO00633
AC02569	51200	60.93	60.93 Guide Post Maintenance	31/Oct/2016	1	2	WO00633
AC02009	51200	67.77	67.77 Guide Post Maintenance	07/Jul/2016	2	2	WO00529
AC02608	51200	68.65	68.65 Guide Post Maintenance	01/Nov/2016	2	2	WO00633
AC02609	51200	68.65	68.65 Guide Post Maintenance	01/Nov/2016	1	2	WO00633
AC02570	51200	68.74	68.74 Guide Post Maintenance	31/Oct/2016	1	2	WO00633
AC02010	51200	73.15	73.15 Guide Post Maintenance	07/Jul/2016	X	2	WO00529
AC03607	51200	73.60	73.60 Replaced white post bent.	20/Jul/2017	2	2	
AC02014	51200	73.60	73.60 Guide Post Maintenance	07/Jul/2016	2	2	WO00529
AC03608	51200	73.78	73.78 Replaced yellow and black guideposts.	20/Jul/2017	1	2	
AC03609	51200	73.82	73.82 Replaced yellow and black guideposts bent.	20/Jul/2017	2	2	
AC02012	51200	73.82	73.82 Guide Post Maintenance	07/Jul/2016	X	2	WO00529
AC02011	51200	73.83	73.83 Guide Post Maintenance	07/Jul/2016	1	2	WO00529
AC03612	51200	74.02	74.02 Replaced white guide post over culvert.	20/Jul/2017	2	2	
AC03606	51200	74.05	74.05 Replaced yellow and black guideposts bent.	20/Jul/2017	2	2	
AC02013	51200	74.19	74.19 Guide Post Maintenance	07/Jul/2016	2	2	WO00529
AC03611	51200	74.43	74.43 Replaced 1 yellow and 2 white bent over.	20/Jul/2017	2	2	
AC03610	51200	74.43	74.43 Replaced white guide post bent.	20/Jul/2017	1	2	
AC02610	51200	75.09	75.09 Guide Post Maintenance	01/Nov/2016	1	2	WO00633
AC03602	51200	75.61	75.61 Replaced yellow and black guideposts.	20/Jul/2017	1	2	
AC03603	51200	75.73	75.73 Replaced yellow and black guideposts.	20/Jul/2017	1	2	
AC03605	51200	75.90	75.90 Replaced 1 white post bent.	20/Jul/2017	1	2	
AC03604	51200	76.02	76.02 Replaced 1 yellow and black guideposts plus 1white.	20/Jul/2017	1	2	

Accomplishment Number	Activity	Chainage From	Chainage To	Comments	Date	Lane Code	Schedule	Work Order Number
AC04435	10100	20.16	20.20	Edge Repair	15/Nov/2017	2	2	WO01052
AC04443	10100	20.23	20.32	Edge Repair	15/Nov/2017	2	2	WO01052
AC04352	10100	20.64	20.64	Edge Repair 60mm deep	13/Oct/2017	2	2	WO01052
AC04351	10100	20.65	20.65	Edge Repair 60mm	13/Oct/2017	2	2	WO01052
AC04350	10100	21.15	21.15	Edge Repair	29/Sep/2017	2	2	WO01052
AC04349	10100	21.15	21.15	Edge Repair	29/Sep/2017	2	2	WO01052
AC04436	10100	25.59	25.69	Edge Drop off 150mm deep on sealed shoulder	15/Nov/2017	2	2	WO01052
AC04438	10100	26.30	26.32	Edge drop 70mm	15/Nov/2017	1	2	WO01052
AC04437	10100	27.10	27.10	Edge Break	15/Nov/2017	1	2	WO01052
AC04371	10500	20.06	20.06	Pothole Repair	18/Oct/2017	1	2	
AC04378	10500	20.06	20.06	Pothole Repair	19/Oct/2017	1	2	
AC04424	10500	20.72	20.72	Pothole in driving lane.	08/Nov/2017	1	2	
AC03568	10500	20.89	20.89	pothole	27/Jul/2017	1	2	WO00894
AC04512	10500	23.00	76.00	Pothole Repair	30/Nov/2017	X	2	WO01077
AC04374	10500	25.19	25.19	Pothole Repair	19/Oct/2017	1	2	
AC04375	10500	25.44	25.44	Pothole Repair	19/Oct/2017	1	2	
AC04372	10500	25.52	25.52	Pothole Repair	19/Oct/2017	1	2	
AC04373	10500	25.62	25.62	Pothole Repair	19/Oct/2017	2	2	
AC04376	10500	26.14	26.14	Pothole Repair	19/Oct/2017	1	2	
AC04377	10500	26.23	26.23	Pothole Repair	19/Oct/2017	1	2	
AC04877	10500	27.40	27.40	Pothole	28/Feb/2018	2	2	WO01206
AC04495	10500	37.57	37.57	Isolated pothole	23/Nov/2017	2	2	WO01112
AC04494	10500	38.80	38.80	Pothole Repair	23/Nov/2017	2	2	
AC03952	10500	39.51	39.51	Pothole	07/Sep/2017	1	2	WO01017
AC03953	10500	44.91	44.91	Pothole	07/Sep/2017	1	2	WO01017
AC04686	10500	46.73	46.73	Pothole	19/Jan/2018	1	2	WO01137
AC04485	10500	51.55	51.55	Pothole Repair	23/Nov/2017	1	2	WO01112
AC04493	10500	52.55	52.55	Pothole Repair	23/Nov/2017	2	2	
AC03954	10500	54.08	54.08	Pothole Repair	07/Sep/2017	2	2	
AC04281	10500	54.10	54.10	Pothole	29/Sep/2017	1	2	WO01017
AC04687	10500	56.41	56.41	Pothole	19/Jan/2018	1	2	WO01137
AC04876	10500	56.57	56.57	Pothole	27/Feb/2018	1	2	WO01206
AC04873	10500	57.55	57.55	Pothole	27/Feb/2018	2	2	WO01206
AC03955	10500	60.40	60.40	isolated pothole in wheel track	07/Sep/2017	1	2	WO01017
AC04492	10500	62.06	62.06	Pothole on top of failure.	23/Nov/2017	2	2	
AC04491	10500	62.72	62.72	Pothole Repair	23/Nov/2017	2	2	
AC04688	10500	62.89	62.89	Potholes	19/Jan/2018	1	2	WO01137
AC04486	10500	63.32	63.32	Pothole Repair	23/Nov/2017	1	2	WO01112
AC03567	10500	64.10	64.13	Potholes	27/Jul/2017	X	2	WO00894
AC04875	10500	64.37	64.37	Pothole Repair	27/Feb/2018	1	2	WO01206
AC04496	10500	65.08	65.08	Pothole Repair	23/Nov/2017	1	2	WO01112
AC04487	10500	65.10	65.10	Pothole is on Rd. Failure.	23/Nov/2017	1	2	WO01112
AC04488	10500	65.23	65.23	Pothole	23/Nov/2017	1	2	WO01112
AC04489	10500	67.12	67.12	Pothole caused by collapsed pipe under rd. Has been covered previously.	23/Nov/2017	1	2	
AC04497	10500	67.12	67.12	Pothole Repair	23/Nov/2017	1	2	WO01112
AC04502	10500	67.13	67.13	Repaired pothole from collapsed pipe that was repaired earlier.	24/Nov/2017	1	2	

AC04656	13900	24.80	24.81 Debris on Roadway	12/Jan/2018	X	2	WO01076
AC04773	14350	62.08	62.08 Shoving 4 x 2	06/Feb/2018	2	2	WO01169
AC04774	14350	62.21	62.21 6x2m	06/Feb/2018	2	2	WO01169
AC04874	14350	65.05	65.05 Failure 8x1	27/Feb/2018	1	2	
AC04565	16900	67.11	67.11 Defect cause by pipe seperation 1x2 failure (pothole)	11/Dec/2017	1	2	WO01117
AC18040	30500	21.14	21.14 Drainage Maintenance	12/Apr/2018	U	2	
AC04597	31900	31.555	31.555 Drainage Maintenance	05/Jan/2018	X	2	WO01082
AC18595	31900	32.32	32.32 Drainage Maintenance	07/Jun/2018	2	2	WO01250
AC18555	31900	67.00	67.00 Inspect Drainage (Work did not Commence)	05/Jun/2018	X	2	WO01252
AC18507	32000	41.83	41.83 extend double barrel 450mm pipe x 1 reinforce & reinstate batter	29/May/2018	U		JMRA
AC18506	32900	41.83	41.83 scoured shoulder over culvert undermining roadway	29/May/2018	U	2	
AC18498	40100	23.347	76.426 Roadside Slashing	24/May/2018	X	2	WO01201
AC04499	40100	23.347	76.426 Slashing Dawson Hwy	24/Nov/2017	X	2	WO00980
AC18474	40100	23.347	76.426 Slashing Dawson Hwy	22/May/2018	X	2	WO01288
AC18666	40500	22.02	22.02 8 small trees in inlet	14/Jun/2018	X	2	WO01255
AC18683	40500	22.61	22.61 Tree limbs obstructing slasher travel path	14/Jun/2018	1	2	WO01255
AC18686	40500	23.93	23.93 1 x medium tree in inlet	14/Jun/2018	X	2	WO01255
AC18687	40500	24.20	24.20 Tree on slasher travel path	14/Jun/2018	X	2	WO01255
AC18667	40500	24.52	24.52 Tree in slasher travel path	14/Jun/2018	X	2	WO01255
AC18665	40500	26.07	26.07 Tree limbs obstructing slasher travel path	14/Jun/2018	X	2	WO01255
AC18685	40500	27.60	27.60 Suckeres in slasher travel path	14/Jun/2018	X	2	WO01255
AC18664	40500	31.44	31.50 Shrubs overhanging shoulder and in way of slasher at Deep Creek bridge approach	14/Jun/2018	X	2	WO01255
AC04132	40500	32.00	32.00 Tree Over Road	27/Sep/2017	X	2	WO01005
AC18682	40500	33.42	33.42 Fallen tree obstructing tabledran	14/Jun/2018	1	2	WO01255
AC03951	40500	36.00	37.75 Clearing	07/Sep/2017	X	2	
AC04383	40500	36.10	37.75 Clearing	25/Oct/2017	X	2	WO00946
AC18668	40500	36.18	36.40 Suckers close to roadway in slasher path	14/Jun/2018	X	2	WO01255
AC18684	40500	41.18	41.35 Suckeres in slasher travel path	14/Jun/2018	2	2	WO01255
AC03744	40700	23.34	76.426 can't be slashed due placed rock in drain and All Herbicide Spraying Required On Dawson Hwy	24/Jul/2017	2	2	WO00873
AC18715	42000	23.347	70.00 Western Road Services Litter Collection	29/Jun/2018	X	2	WO01043
AC03774	45000	21.30	21.30 Call Out to Oil Spill on Dawson Hwy	28/Jul/2017	1	6	WO00924
AC03768	45000	21.75	23.347 Call Out Cattle on Road Dawson Hwy	28/Jul/2017	X	6	WO00900
AC04439	45000	21.75	25.69 Call Out	15/Nov/2017	X	6	WO01059
AC03666	45000	22.313	23.947 Call Out Cattle on Road Dawson Hwy	10/Jul/2017	X	6	WO00881
AC04564	45000	23.347	25.69 Call Out Cattle on Road Dawson Hwy - csr 502543	11/Dec/2017	X	6	WO01089
AC03775	45000	25.69	30.128 Call Out Cattle on Road Dawson Hwy	28/Jul/2017	X	6	WO00930
AC18718	45000	34.059	36.99 Call Out Cattle on Road	29/Jun/2018	X	6	WO01282
AC04689	45000	43.606	43.606 DTMR Requested Message board to close Dawson Hwy	19/Jan/2018	X	6	WO01131
AC04562	45000	43.606	43.606 CSR 500714 - Police request to supply "road closed" signs as flood water over the road - Jayson Keyworth atte	11/Dec/2017	X	6	WO01090
AC04601	45000	50.51	55.258 CSR 506147- call out cattle on road - Out of hours contractor attended	08/Jan/2018	X	6	WO01104
AC04808	45000	53.00	53.00 Call Out Tree Over Road	14/Feb/2018	X	6	WO01144
AC04596	45000	54.27	54.27 Call Out	04/Jan/2018	1	6	
AC03857	45000	64.087	69.406 Call Out	21/Aug/2017	X	6	WO00951
AC04514	45200	22.80	22.80 Call Out - Road Closed Sign Required	30/Nov/2017	1	6	WO01078
AC04285	50200	20.17	20.17 Clean Keep Left sign on median	05/Oct/2017	X	2	WO00999
AC04286	50200	20.32	20.32 Replace keep left sign and post	05/Oct/2017	X	2	WO00999
AC04649	50200	21.32	21.32 No parking sign 2x right arrow ? Should be 1 x left & 1 x right R5-35	09/Jan/2018	2	2	WO01153

AC04648	50200	21.32	21.32 No parking sign faded 1x LEFT 1X RIGHT arrow R5-35	09/Jan/2018	2	2	WO01153
AC18556	50200	21.41	21.41 DUPLICATE	05/Jun/2018	2	2	
AC04282	50200	21.53	21.53 NO STOPPING Sign Faded R5-35	05/Oct/2017	2	2	WO00999
AC04283	50200	28.09	28.09 Replace school bus rout sign post ok	05/Oct/2017	1	2	WO00999
AC04284	50200	30.37	30.37 REPLACE SIGN SCHOOL BUS ROUT	05/Oct/2017	1	2	WO00999
AC04288	50200	42.47	42.47 Replace school bus rout sign	06/Oct/2017	1	2	WO00999
AC04776	50900	21.309	21.309 Sign knocked	08/Feb/2018	X	2	WO01183
AC04777	50900	21.594	21.594 Sign knocked	08/Feb/2018	X	2	WO01183
AC03676	51200	19.72	19.72 Guide Post Maintenance	12/Jul/2017	2	2	WO00927
AC04507	51200	19.88	19.88 Replaced guide post with flexible post.	29/Nov/2017	2	2	
AC04770	51200	19.89	19.89 Replace guidpost	05/Feb/2018	2	2	WO01116
AC18559	51200	20.65	20.65 Replace guide post	06/Jun/2018	2	2	WO01306
AC18560	51200	20.65	20.65 Replace guide post over culvert	06/Jun/2018	1	2	WO01306
AC03677	51200	21.81	21.81 Guide Post Maintenance	12/Jul/2017	1	2	
AC03679	51200	22.13	22.13 Guide Post Maintenance	12/Jul/2017	1	2	
AC03678	51200	22.20	22.20 Guide Post Maintenance	12/Jul/2017	1	2	
AC04508	51200	23.22	23.22 Guide Post Maintenance	29/Nov/2017	1	2	
AC04771	51200	23.27	23.27 Replace flexible guidpost	05/Feb/2018	1	2	WO01116
AC03680	51200	23.88	23.88 Guide Post Maintenance	12/Jul/2017	1	2	
AC04853	51200	23.90	23.90 Missing guidepost	22/Feb/2018	X	2	WO01191
AC18561	51200	23.90	23.90 Replace guide post	06/Jun/2018	2	2	WO01306
AC04854	51200	24.29	24.29 Missing guideposts	22/Feb/2018	X	2	WO01191
AC03685	51200	24.44	24.44 Guide Post Maintenance	12/Jul/2017	2	2	
AC03681	51200	24.98	24.98 Guide Post Maintenance	12/Jul/2017	2	2	
AC04769	51200	25.58	25.58 Replace guidepost	05/Feb/2018	1	2	WO01116
AC04839	51200	25.59	25.59 Guide Post Maintenance	21/Feb/2018	1	2	
AC03758	51200	27.03	27.03 guidepost replace	27/Jul/2017	1	2	WO00927
AC04768	51200	33.98	33.98 Replace the guidepost	05/Feb/2018	2	2	WO01116
AC18562	51200	34.86	34.86 Replace guide post	06/Jun/2018	1	2	WO01306
AC04855	51200	34.97	34.97 Missing guidepost	22/Feb/2018	X	2	WO01191
AC04840	51200	35.19	35.19 Guide Post Maintenance	21/Feb/2018	1	2	
AC04856	51200	35.58	35.58 Missing guidepost	22/Feb/2018	X	2	WO01191
AC03682	51200	36.39	36.39 Guide Post Maintenance	12/Jul/2017	1	2	
AC03683	51200	36.52	36.52 Guide Post Maintenance	12/Jul/2017	2	2	
AC04736	51200	37.56	37.56 Replace guidepost	31/Jan/2018	1	2	WO01116
AC04737	51200	38.01	38.01 Replace guidepost	31/Jan/2018	2	2	WO01116
AC03684	51200	38.55	38.55 Guide Post Maintenance	12/Jul/2017	1	2	
AC18578	51200	39.60	39.60 Replace guide post	06/Jun/2018	1	2	WO01306
AC18563	51200	40.30	40.30 Replace guide post	06/Jun/2018	1	2	WO01306
AC18564	51200	40.52	40.52 Replace guide post	06/Jun/2018	1	2	WO01306
AC18566	51200	40.65	40.65 Replace guide post	06/Jun/2018	1	2	WO01306
AC18565	51200	40.65	40.65 Replace guide post	06/Jun/2018	1	2	WO01306
AC04738	51200	40.70	40.70 Replacing guidepost	31/Jan/2018	1	2	WO01116
AC04852	51200	45.49	45.49 Replace guidepost	22/Feb/2018	X	2	WO01191
AC18577	51200	47.02	47.02 Missing guide post	06/Jun/2018	1	2	WO01306
AC18567	51200	50.22	50.22 Replace guide post	06/Jun/2018	2	2	WO01306
AC18568	51200	50.28	50.28 Replace guide post	06/Jun/2018	2	2	WO01306

AC18569	51200	51.87	51.87 Replace guide post	06/Jun/2018	2	WO01306
AC18576	51200	52.48	52.48 Replace guide post	06/Jun/2018	2	WO01306
AC18570	51200	53.80	53.80 Replace guide post	06/Jun/2018	2	WO01306
AC18571	51200	57.91	57.91 Replace guide post	06/Jun/2018	1	WO01306
AC18572	51200	60.86	60.86 Replace guidepost	06/Jun/2018	1	WO01306
AC18573	51200	61.15	61.15 Replace guidepost	06/Jun/2018	1	WO01306
AC18574	51200	63.22	63.22 Replace guide post	06/Jun/2018	1	WO01306
AC04739	51200	67.24	67.24 Replace guidepost	31/Jan/2018	2	WO01116
AC18575	51200	67.90	67.90 Replace guide post	06/Jun/2018	2	WO01306
AC04490	51200	69.68	69.68 Replace bolted round guidpost 1x white 1x yellow and black	23/Nov/2017	1	WO01116
AC03688	51200	73.61	73.61 Guide Post Maintenance	12/Jul/2017	1	
AC03689	51200	73.61	73.61 Guide Post Maintenance	12/Jul/2017	2	
AC03690	51200	73.79	73.79 Guide Post Maintenance	12/Jul/2017	1	
AC03687	51200	73.80	73.80 Yellow post to long needs cutting shorter.	12/Jul/2017	1	WO00927
AC03691	51200	75.07	75.07 Replaced white post but yellow needs cutting down.	12/Jul/2017	1	
AC03686	51200	76.02	76.02 Could only replace white post yellow needs cutting of to suit.	12/Jul/2017	1	WO00927
AC04509	51200	76.03	76.03 Replaced one yellow and white guide post.	29/Nov/2017	1	
AC04526	51200	76.26	76.26 Replaced one yellow and white guide post.	30/Nov/2017	1	
AC04510	51200	76.39	76.39 Replaced one yellow and white guide post.	29/Nov/2017	1	
AC04511	51200	76.43	76.43 Replaced one yellow and black guideposts.	29/Nov/2017	1	
AC04741	51200	76.47	76.47 Replace bolted round guidpost 1x yellow and black	31/Jan/2018	1	WO01116
AC04742	51200	76.47	76.47 Replace bolted round guidpost 1x whit 1x yellow & black	31/Jan/2018	1	WO01116
AC04740	51200	76.47	76.47 Replace bolted round guidpost 1x white 1x yellow and black	31/Jan/2018	1	WO01116
AC04287	52200	19.52	19.52 Installed 2x posts and vehile access only sign	06/Oct/2017	2	
AC18706	75900	21.50	21.60 Line Marking	29/Jun/2018	X	WO01270
AC18603	75900	21.651	21.75 Line Marking As Instructed DTMR Dawson Hwy	08/Jun/2018	X	WO01244

Released under RTI - DTMR

Accomplishment Number	Activity	Chainage From	Chainage To	Comments	Date	Lane Code	Schedule	Work Order Number
AC18807	10500	27.38	27.38	Pothole Repair	23/Jul/2018	2	1	WO01363
AC18808	10500	37.15	37.15	Pothole	23/Jul/2018	1	1	WO01363
AC18748	10500	37.56	37.56	Pothole Repair	23/Jul/2018	2	1	WO01363
AC18811	10500	43.04	43.04	Pothole	23/Jul/2018	2	1	WO01363
AC18810	10500	43.04	43.04	Pothole Repair	23/Jul/2018	2	1	WO01363
AC18821	10500	43.12	43.12	Pothole Repair	06/Aug/2018	2	1	WO01363
AC18809	10500	43.12	43.12	Pothole Repair	23/Jul/2018	2	1	WO01363
AC18812	10500	45.04	45.04	Pothole Repair	23/Jul/2018	1	1	WO01363
AC18813	10500	46.06	46.06	Pothole Repair	23/Jul/2018	1	1	WO01363
AC18814	10500	51.49	51.49	Pothole	23/Jul/2018	1	1	WO01363
AC18815	10500	54.10	54.10	Pothole Repair	23/Jul/2018	1	1	WO01363
AC18816	10500	56.36	56.36	Pothole Repair	23/Jul/2018	1	1	WO01363
AC18747	10500	58.41	58.41	Pothole Repair	23/Jul/2018	2	1	WO01363
AC18817	10500	59.58	59.58	Pothole Repair	23/Jul/2018	1	1	WO01363
AC18818	10500	62.91	62.91	Pothole Repair	23/Jul/2018	1	1	WO01363
AC18819	10500	63.31	63.31	Pothole Repair	23/Jul/2018	1	1	WO01363
AC18820	10500	65.07	65.07	Pothole Repair	23/Jul/2018	1	1	WO01363
AC18822	10500	67.12	67.12	Pothole Repair	23/Jul/2018	1	1	WO01363
AC18823	10500	71.73	71.73	Pothole Repair	23/Jul/2018	1	1	WO01363
AC18824	10500	72.79	72.79	Pothole Repair	23/Jul/2018	1	1	WO01363
AC18904	40100	23.00	76.426	Slashing Dawson Hwy	10/Aug/2018	X	1	WO01332
AC18591	42900	23.347	70.00	Western Road Services Litter Collection	13/Jul/2018	X	1	WO01043
AC21758	45000	25.69	27.224	Call Out Cattle on Road Dawson Hwy	13/Sep/2018	X	5	WO01362
AC18602	45000	30.128	34.059	Call Out Cattle on Road Dawson Hwy	13/Jul/2018	X	5	WO01305
AC18751	45000	34.059	36.99	Call Out Cattle on Road	24/Jul/2018	X	5	WO01282
AC21759	45000	36.99	39.908	Call Out Cattle on Road Dawson Hwy	14/Sep/2018	X	5	WO01367
AC18758	45000	56.08	64.087	Date: 12/06/2018 Road: Dawson Hwy Suburb: Mt Alma Chainage: Start 56.080 Chainage End 64.087 CSR	25/Jul/2018	X	5	WO01313
AC18724	50900	60.53	60.53	Crest sign knocked down sign ok new post required	17/Jul/2018	2	1	WO01352
AC18838	51200	20.65	20.65	Missing guidepost installed new guide post	07/Aug/2018	1	1	WO01376
AC18561	51200	24.10	24.10	Replace guide post	06/Jun/2018	2	1	WO01306
AC18578	51200	25.10	76.00	Replace guide post	06/Jun/2018	X	1	WO01306
AC18832	51200	25.75	25.75	Installed 1 x new guide post	07/Aug/2018	1	1	WO01376
AC18833	51200	39.08	39.08	Replace guide post	07/Aug/2018	1	1	WO01376
AC18837	51200	40.75	40.75	Replace guide post	07/Aug/2018	1	1	WO01376
AC18834	51200	44.36	44.36	Replace guide post	07/Aug/2018	2	1	WO01376
AC18835	51200	50.28	50.28	Replace guide post	07/Aug/2018	2	1	WO01376
AC18836	51200	61.13	61.13	Replace guidepost	07/Aug/2018	1	1	WO01376
AC18595	75900	21.50	21.60	Line Marking	13/Jul/2018	X	3	WO01270